

Configuration Description	Code	Control		Motion			List Price
		Input Range	Position Feedback	Running Time	Torque %	Adaptation	
<input type="checkbox"/> P-10001	A01	2.0 to 10.0 VDC	2.0 to 10.0 VDC	150	100	Manual	No Charge*
<input type="checkbox"/> P-10002	A02	0.0 to 10.0 VDC	0.0 to 10.0 VDC	150	100	Manual	No Charge
<input type="checkbox"/> P-10003	A03	2.0 to 10.0 VDC	0.0 to 5.0 VDC	150	100	Manual	No Charge
<input type="checkbox"/> P-10004	A04	4.0 to 7.0 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10005	A05	6.0 to 9.0 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10006	A06	10.5 to 13.5 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10007	A07	0.0 to 5.0 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10009	A09	5.0 to 10.0 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10010	A10	5.0 to 10.0 VDC	0.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10013	A13	0.0 to 10.0 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10015	A15	2.0 to 5.0 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10016	A16	2.0 to 6.0 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10017	A17	6.0 to 10.0 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10018	A18	14.0 to 17.0 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10020	A20	9.0 to 12.0 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10028	A28	0.0 to 10.0 VDC	0.0 to 10.0 VDC	100	100	Manual	No Charge
<input type="checkbox"/> P-10031	A31	0.0 to 4.0 VDC	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-10063	A63	0.5 to 4.5 VDC	0.5 to 4.5 VDC	150	100	Manual	No Charge
<input type="checkbox"/> P-10064	A64	5.5 to 10.0 VDC	5.5 to 10.0 VDC	150	100	Manual	No Charge
<input type="checkbox"/> P-20001	W01	0.59 to 2.93 sec.	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-20002	W02	0.02 to 5.00 sec.	2.0 to 10.0 VDC	150	100	Manual	No Charge
<input type="checkbox"/> P-20003	W03	0.10 to 25.50 sec.	2.0 to 10.0 VDC	150	100	Manual	No Charge
<input type="checkbox"/> P-20004	W04	0.10 to 25.60 sec.	2.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-20005	W05	0.10 to 5.20 sec.	0.0 to 5.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-30001	F01	Floating point	2.0 to 10.0 VDC	150	100	Manual	No Charge
<input type="checkbox"/> P-30002	F02	Floating point	0.0 to 10.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-30003	F03	Floating point	2.0 to 10.0 VDC	100	100	Manual	\$ 30.00
<input type="checkbox"/> P-30004	F04	Floating point	0.0 to 5.0 VDC	100	100	Manual	\$ 30.00
<input type="checkbox"/> P-30005	F05	Floating point	0.0 to 10.0 VDC	100	100	Manual	\$ 30.00
<input type="checkbox"/> P-30006	F06	Floating point	0.0 to 5.0 VDC	150	100	Manual	\$ 30.00
<input type="checkbox"/> P-40001	J01	On/Off	2.0 to 10.0 VDC	75	100	Manual	\$ 30.00
<input type="checkbox"/> P-40002	J02	On/Off	2.0 to 10.0 VDC	150	100	Manual	No Charge
<input type="checkbox"/> P-40003	J03	On/Off	2.0 to 10.0 VDC	75	100	Manual	\$ 30.00
<input type="checkbox"/> P-40004	J04	On/Off	0.0 to 5.0 VDC	100	100	Manual	\$ 30.00
<input type="checkbox"/> P-40005	J05	On/Off	0.0 to 10.0 VDC	100	100	Manual	\$ 30.00

*P-10001 is the default configuration.