Pressure Transmitter

Zone Pressure Sensors (ZPS)

Rev. 11/01/05

Features & Options

- 5 Direct and 5 Bi-Directional Standard Ranges
- Inches of Water Column (W.C.) or Pascal Operation
- 4 to 20 mA, 0 to 5 VDC, or 0 to 10 VDC Output
- Pressure Range and Output Settings are Field Selectable
- Microprocessor Controlled Auto-Zero
- Rugged (IP66 rated) Housing
- Fits Standard 1/8" I.D. or 1/4" I.D. Tubing
- Mounting Tabs for Easy Installation
- Three Year Warranty
- Applications:

Duct, Room or Building Static Pressure
Air Velocity and Volume • Air Filter Pressure Drop
Coil Airflow Monitoring • Room-to-Room Differential Pressure
Exhaust Fan Control

BAPI's Zone Pressure Transmitter is an accurate, rugged and economical solution for measuring and reporting duct/building static pressure, room-to-room differential pressure or air velocities/volumes. The heart of the unit is a micro-machined silicon piezoresistive pressure sensor specifically developed for low pressure. The sensor receives a five-point error correction over the compensated temperature range for excellent accuracy, repeatability and stability.

The pressure sensor's custom ASIC (Application Specific Integrated Circuit) provides error correction and signal amplification using digital compensation while maintaining an analog signal path—a unique design among piezoresistive sensor products. This technique provides both the high level of error correction found in microprocessor-based circuits and the high bandwidth generally found only in analog circuits. The result is a pressure sensor that offers the ultimate in high accuracy, while preserving the fast response and smooth output inherent to silicon sensors.

With an easy-mounting, rugged enclosure and short circuit proof output and reverse polarity protected inputs, this device is built to perform under real world conditions. The unit installs quickly by connecting standard 1/8" or 1/4" tubing to the two pressure ports. The various Output Ranges and Pressure Ranges are all field selectable with DIP switches, and the auto-zeroing process is microprocessor-controlled for simplicity (flip a switch, wait five seconds, flip it back and walk away).

The optional Static Pressure Probe Assembly connects to the high port of the Zone Pressure Sensor. The probe includes a built in surge damper which smoothes out the airflow signals or room pressure signals for a more stable reading.





Zone Pressure Transmitter



Optional Static Pressure Probe Assembly

Specifications Material: ABS Plastic Rating: IP 66 Environmental Specifications: Temperature: 32 to 140 °F (0 to 60 °C) Humidity: 0 to 95%, non-condensing 2.13" (54.1mm) (96.5mm) (104.4mm) Zone Pressure Transmitter

Optional Static Pressure Probe Assembly



Pressure Transmitter

Zone Pressure Sensors (ZPS)

Rev. 11/01/05

Specifications

Power:

8.5 to 45 VDC (4-20 mA output)

8.5 to 45 VDC or 8.5 to 32 VAC (0-5 VDC output) 13 to 45 VDC or 13 to 32 VAC (0-10 VDC output)

Load Resistance:

Voltage Output - 1 k Ω minimum Current Output - 500 Ω max. (depending on available voltage)

Power Consumption: .53 VA maximum

Accuracy:

 $\pm 1\%$ on 0 to 0.1 range and ± 0.1 range,

±0.5% on other ranges

Stability: ±2 % F.S. (full scale) per year

Temperature Error:

Zero - ±0.025% F.S. per °C, Span - max ±0.03% F.S. per °C

Environmental Specifications:

Temperature: -13 to 176 °F (-25 to 80 °C) 32 to 140 °F (0 to 60 °C)

compensated range

Humidity: 0 to 95% RH, non-condensing

Wiring:

*2 (loop powered) or 3 (AC powered) wires

Overpressure:

Proof - 5 PSI, Burst - 10 PSI

Optional Field Mounting Kit

For more information, see page C8.



ZPS with Field Mounting Kit

* BAPI recommends that you do not run wiring for the pressure transmitter in the same conduit as line voltage wiring or with wiring used to supply highly inductive loads such as motors, generators, and coils. Note: Mount unit with the pressure fittings on the bottom to prevent condensation from entering the sensor.

Outro	t Dance I							
	t Range ‡							
-20	4 to 20 mA	,	(8.5 to 45 VDC Supply ONLY)					
-05	0 to 5 V	· · · · · · · · · · · · · · · · · · ·						
-10	0 to 10 V (13 to 45 VDC Supply or 13 to 32 VAC Supply)							
	Pressure Range ‡							
	-SR(range)	Standard Pressure Ranges - replace (range) with option # shown below						
		Option	Range (inche	es W.C.)		Option	Range (Pascals)	
		01	0 to 0.10			11	0 to 25	
		02	0 to 0.25			12	0 to 50	
		03	0 to 1.00			13	0 to 300	
		04	0 to 2.50			14	0 to 500	
		05	0 to 5.00			15	0 to 1,000	
		06	-0.10 to 0.10			16	-25 to 25	
		07	-0.25 to 0.25			17	-50 to 50	
		08	-1.00 to 1.00			18	-300 to 300	
		09 10	-2.50 to 2.50 -5.00 to 5.00			19 20	-500 to 500 -1,000 to 1,000	
		10	-5.00 10 5.00	,		20	-1,000 to 1,000	
			Custom Range	ge (W.C.)			Custom Range (Pascals)	
		CI	[x.xx to y.yy]*			CP	[xxxx to yyyy]**	
			ry Options					
		-NT	No Tube or F					
		-ST	Static Pressu					
			Pressure	_				
			-125		epts 1/8" I.D.			
			-250		epts 1/4" I.D.			
			Mounting Kits (Optional)					
				-FMK Field Mounting Kit				
				-FM	1/2" condui		nly	
				-PM	Panel Mour	nt		
MPLE					_			
-20	-SR01	-NT	-125	-FMK				
nple Part I	Number: ZPS-20-	SR01-NT-125	5-FMK					

^{*}For custom W.C. ranges, x.xx and y.yy can be any pressure from -5.00 to +5.00 inches W.C. However, x.xx must be less than y.yy and y.yy - x.xx must be at least .1 inches. (Example Part #: ZPS-20-SRCI[0.00 to 3.00]-NT-250-D

^{**}For custom Pascal ranges, xxxx and yyyy can be any pressure from -1250 to +1250 Pascals. However, xxxx must be less than yyyy and yyyy - xxxx must be at least 25 Pascals. (Example Part #: ZPS-20-SRCP[0 to 100]-NT-250-D

Custom output ranges and higher accuracy units are available. Contact BAPI for details.